



#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Serial No.:

10/705,350

Filed:

November 10, 2003

Patent No.:

6,866,153 B 2

Issued:

March 15, 2005

Applicant(s):

Richard R. Turner, Jr., Robert Kircher, Dennis R. Moran, James P. Dugan

Title:

DISPOSABLE NET ASSEMBLIES FOR APPARATUS FOR COLLECTING

FLOATING DEBRIS

Commissioner for Patents P.O. Box 1450

Alexandria, VA 22313-1450

Certificate

FEB 0 2 2006

ATTN:

DECISION AND CERTIFICATE OF CORRECTION

of Correction

BRANCH OF THE PATENT ISSUE DIVISION

#### REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 CFR §1.322 (a))

Sir:

Attached in duplicate form, is Form PTO-1050, with at least one copy being suitable for printing. The errors which appear in the Form PTO-1050 were typographical errors which occurred through the fault of the U.S. Patent and Trademark Office ("PTO").

The exact column and line number where the errors are shown in the patent are as follows:

Column 2, line 13 reads "...maybe configured such that, upon filling of the first trap..." and should read - ...may be configured such that, upon filling of the first trap... - .

Column 9, line 61 reads "...prises the two side members each having an unpstream and..." and should read – ...prises the two side members, each having an upstream and... – .

Column 10, lines 1-2 read "12. The assembly of claim 11 wherein the at least two members having the two side members each has an upstream..." and should read—12. The assembly of claim 11 wherein the two side members each has an upstream...

Column 10, lines 5-6 read "13. The assembly of claim 12 wherein the at least two members having the two side members each has an outside..." and should read -13. The assembly of claim 12 wherein the two side members each has an outside... -.

Column 10, lines 9-10 read "14. The assembly of claim 13 wherein the at least two members having the two side members each has an inside..." and should read -14. The assembly of claim 13 wherein the two side members each has an inside... -.

Column 10, lines 13-14 read "15. The assembly of claim 12 wherein the at least two members having the two side members each has an inside..." and should read – 15. The assembly of claim 12 wherein the two side members each has an inside... – .

Column 10, lines 17-18 read "16. The assembly of claim 11 wherein the at least two members having the two side members each has an inside..." and should read – 16. The assembly of claim 11 wherein the two side members each has an inside... – .

Column 10, lines 25-26 read "18. The assembly of claim 17 wherein the at least two members having the two side members each has an outside..." and should read -18. The assembly of claim 17 wherein the two side members each has an outside... -.

Column 10, lines 29-30 read "19. The assembly of claim 18 wherein the at least two members having the two side members each has an upstream..." and should read – 19. The assembly of claim 18 wherein the two side members each has an upstream...

Column 10, lines 34-35 read "20. The assembly of claim 18 wherein the at least two members having the two side members each has an upstream..." and should read – 20. The assembly of claim 18 wherein the two side members each has an upstream...

Column 10, lines 36-37 read "21. The assembly of claim 17 wherein the at least two members having the two side members each has an upstream..." and should read – 21. The assembly of claim 17 wherein the two side members each has an upstream...

Column 10, lines 40-41 read "22. The assembly of claim 10 wherein the at least two members having the two side members each has an upstream..." and should read –

22. The assembly of claim 10 wherein the two side members each has an upstream...

Column 10, lines 44-45 read "23. The assembly of claim 22 wherein the at least two members having the two side members each has an outside..." and should read -23. The assembly of claim 22 wherein the two side members each has an outside... -.

Column 10, line 50 reads "...prises the two side members each having an outside thereof..." and should read – ... prises the two side members, each having an outside thereof... – .

Column 10, lines 53-54 read "25. The assembly of claim 24 wherein the at least two members having the two side members each has an upstream..." and should read – 25. The assembly of claim 24 wherein the two side members each has an upstream...

Column 10, lines 57-58 read "26. The assembly of claim 25 wherein the at least two members having the two side members each has an inside..." and should read -26. The assembly of claim 25 wherein the two side members each has an inside... -.

Please send the certificate to:

Joseph R. Jordan, Esq. Wood, Herron & Evans, L.L.P. 2700 Carew Tower Cincinnati, Ohio 45202

If there is any further charge or credit due, please use Deposit Account No. 23-3000.

Respectfully submitted,

WOOD, HERRON & EVANS, L.L.P.

Red No. 25,686

WOOD, HERRON & EVANS, L.L.P.

2700 Carew Tower Cincinnati, Ohio 45202

(513) 241-2324

### UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,866,153 B 2

DATED : March 15, 2005

INVENTOR(S): Richard R. Turner, Jr., Robert Kircher, Dennis R. Moran, James P.

Dugan

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2, line 13 reads "...maybe configured such that, upon filling of the first trap..." and should read - ...may be configured such that, upon filling of the first trap... - .

Column 9, line 61 reads "...prises the two side members each having an unpstream and..." and should read – ...prises the two side members, each having an upstream and... – .

Column 10, lines 1-2 read "12. The assembly of claim 11 wherein the at least two members having the two side members each has an upstream..." and should read -12. The assembly of claim 11 wherein the two side members each has an upstream... -.

Column 10, lines 5-6 read "13. The assembly of claim 12 wherein the at least two members having the two side members each has an outside..." and should read – 13. The assembly of claim 12 wherein the two side members each has an outside... – .

Column 10, lines 9-10 read "14. The assembly of claim 13 wherein the at least two members having the two side members each has an inside..." and should read -14. The assembly of claim 13 wherein the two side members each has an inside... -.

Column 10, lines 13-14 read "15. The assembly of claim 12 wherein the at least two members having the two side members each has an inside..." and should read -15. The assembly of claim 12 wherein the two side members each has an inside... -.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,866,153</u> No. of add'l copies

@ 50¢ per page:

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street Cincinnati, OH 45202-2917

Page 1 of 3

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,866,153 132

DATED : March 15, 2005 .

INVENTOR(S): Richard R. Turner, Jr., Robert Kircher, Dennis R. Moran, James P. Dugan

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10, lines 17-18 read "16. The assembly of claim 11 wherein the at least two members having the two side members each has an inside..." and should read – 16. The assembly of claim 11 wherein the two side members each has an inside... – .

Column 10, lines 25-26 read "18. The assembly of claim 17 wherein the at least two members having the two side members each has an outside..." and should read -18. The assembly of claim 17 wherein the two side members each has an outside... -.

Column 10, lines 29-30 read "19. The assembly of claim 18 wherein the at least two members having the two side members each has an upstream..." and should read – 19. The assembly of claim 18 wherein the two side members each has an upstream... – .

Column 10, lines 34-35 read "20. The assembly of claim 18 wherein the at least two members having the two side members each has an upstream..." and should read -20. The assembly of claim 18 wherein the two side members each has an upstream... - .

Column 10, lines 36-37 read "21. The assembly of claim 17 wherein the at least two members having the two side members each has an upstream..." and should read -21. The assembly of claim 17 wherein the two side members each has an upstream... – .

Column 10, lines 40-41 read "22. The assembly of claim 10 wherein the at least two members having the two side members each has an upstream..." and should read -22. The assembly of claim 10 wherein the two side members each has an upstream... -.

Column 10, lines 44-45 read "23. The assembly of claim 22 wherein the at least two members having the two side members each has an outside..." and should read – 23. The assembly of claim 22 wherein the two side members each has an outside... – .

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,866,153</u> No. of add'l copies

@ 50¢ per page: \_

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street

Cincinnati, OH 45202-2917

Page 2 of 3

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,866,153 B2-

DATED : March 15, 2005

INVENTOR(S): Richard R. Turner, Jr., Robert Kircher, Dennis R. Moran,

James P. Dugan

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10, line 50 reads "... prises the two side members each having an outside thereof..." and should read – ... prises the two side members, each having an outside thereof... – .

Column 10, lines 53-54 read "25. The assembly of claim 24 wherein the at least two members having the two side members each has an upstream..." and should read – 25. The assembly of claim 24 wherein the two side members each has an upstream... – .

Column 10, lines 57-58 read "26. The assembly of claim 25 wherein the at least two members having the two side members each has an inside..." and should read – 26. The assembly of claim 25 wherein the two side members each has an inside... –

MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street Cincinnati, OH 45202-2917 PATENT NO. 6,866,153 No. of add'l copies

@ 50¢ per page:

Page 3 of 3

#### UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,866,153 B2

DATED : March 15, 2005

INVENTOR(S): Richard R. Turner, Jr., Robert Kircher, Dennis R. Moran, James P.

Dugan

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2, line 13 reads "...maybe configured such that, upon filling of the first trap..." and should read – ...may be configured such that, upon filling of the first trap... – .

Column 9, line 61 reads "... prises the two side members each having an unpstream and..." and should read - ... prises the two side members, each having an upstream and... - .

Column 10, lines 1-2 read "12. The assembly of claim 11 wherein the at least two members having the two side members each has an upstream..." and should read -12. The assembly of claim 11 wherein the two side members each has an upstream... -.

Column 10, lines 5-6 read "13. The assembly of claim 12 wherein the at least two members having the two side members each has an outside..." and should read -13. The assembly of claim 12 wherein the two side members each has an outside... -.

Column 10, lines 9-10 read "14. The assembly of claim 13 wherein the at least two members having the two side members each has an inside..." and should read -14. The assembly of claim 13 wherein the two side members each has an inside... -.

Column 10, lines 13-14 read "15. The assembly of claim 12 wherein the at least two members having the two side members each has an inside..." and should read -15. The assembly of claim 12 wherein the two side members each has an inside... -.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,866,153 No. of add'l copies

@ 50¢ per page:

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street

Cincinnati, OH 45202-2917

Page 1 of 3

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,866,153 B2

DATED : March 15, 2005

INVENTOR(S): Richard R. Turner, Jr., Robert Kircher, Dennis R. Moran,

James P. Dugan

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10, lines 17-18 read "16. The assembly of claim 11 wherein the at least two members having the two side members each has an inside..." and should read - 16. The assembly of claim 11 wherein the two side members each has an inside... - .

Column 10, lines 25-26 read "18. The assembly of claim 17 wherein the at least two members having the two side members each has an outside..." and should read – 18. The assembly of claim 17 wherein the two side members each has an outside... – .

Column 10, lines 29-30 read "19. The assembly of claim 18 wherein the at least two members having the two side members each has an upstream..." and should read -19. The assembly of claim 18 wherein the two side members each has an upstream... -.

Column 10, lines 34-35 read "20. The assembly of claim 18 wherein the at least two members having the two side members each has an upstream..." and should read -20. The assembly of claim 18 wherein the two side members each has an upstream... -.

Column 10, lines 36-37 read "21. The assembly of claim 17 wherein the at least two members having the two side members each has an upstream..." and should read – 21. The assembly of claim 17 wherein the two side members each has an upstream... – .

Column 10, lines 40-41 read "22. The assembly of claim 10 wherein the at least two members having the two side members each has an upstream..." and should read – 22. The assembly of claim 10 wherein the two side members each has an upstream... –

Column 10, lines 44-45 read "23. The assembly of claim 22 wherein the at least two members having the two side members each has an outside..." and should read -23. The assembly of claim 22 wherein the two side members each has an outside... -.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,866,153</u> No. of add'l copies

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street

Cincinnati, OH 45202-2917

@ 50¢ per page:

Page 2 of 3

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,866,153 B2

DATED : March 15, 2005

INVENTOR(S): Richard R. Turner, Jr., Robert Kircher, Dennis R. Moran,

James P. Dugan

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10, line 50 reads "...prises the two side members each having an outside thereof..." and should read - ... prises the two side members, each having an outside thereof... - .

Column 10, lines 53-54 read "25. The assembly of claim 24 wherein the at least two members having the two side members each has an upstream..." and should read -25. The assembly of claim 24 wherein the two side members each has an upstream... -

Column 10, lines 57-58 read "26. The assembly of claim 25 wherein the at least two members having the two side members each has an inside..." and should read -26. The assembly of claim 25 wherein the two side members each has an inside... -.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,866,153 No. of add'l copies @ 50¢ per page:

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street Cincinnati, OH 45202-2917

Page 3 of 3